



## Syscal standard check list

### Device

Syscal switch (Tx and Rx fully charged)  
USB Cable with Syscal Plug  
Syscal user's manual  
[Safety instruction leaflet](#)

### Softs

CD IRIS Instruments with USB Driver  
RES2/3DINV Dongle  
Laptop with [Prosys](#) installed

### Tools

Security Pack  
Electrode Tester  
Battery Tester

### Accessories

Battery chargers + adapters if necessary  
12V External Battery fully charged  
External Battery Cable  
(Red & Black) Alligator Clip (Red & Black)  
Stainless steel Electrodes or Unpolarizable Electrodes  
Cord Clip (3 + number of channels + extras)  
Cables (orange or yellow)  
Reels of cable (1 for pole-dipole, 2 for pole-pole)  
Pole  
Measuring tape (non-metallic)  
GPS  
Hammer  
Voltmeter with two 1m cables  
Salted water + bentonite